Workshop: Ultrasonic Imaging of Concrete Oakland, CA September 12, 2008

# Internal Imaging of Concrete Using Impact Echo Scanning



#### SPECIALIZING IN CONDITION EVALUATION OF THE CIVIL STRUCTURE & INFRASTRUCTURE




www.olsonengineering.com | www.olsoninstruments.com

Patrick K. Miller, Project Engineer Yajai Tinkey, Ph.D., P.E. Larry D. Olson, P.E. Olson Engineering, Inc.

Wheat Ridge, CO - Rutherford, NJ - Hercules, CA - Socorro, NM


#### Impact Echo Test Basic Theory



Workshop: Ultrasonic Imaging of Concrete Oakland, CA September 12, 2008

### Impact Echo Scanner (IES)

- Add wheels to the unit
- Add a rolling transducer
- Calibrated to test every 25 mm or 1" interval
- Speed ~ 20 ft/min




## **Olson Instruments IES System**





Impact Echo Scanner with rolling displacement Transducer and non-contact microphone


Olson Instruments Freedom Data PC and IES-1 system



From a 15" transfer wall


**Typical Data Interpretation - Sound** 

Workshop: Ultrasonic Imaging of Concrete Oakland, CA September <u>12, 2008</u>



Typical Data Interpretation – Poor Consolidation or Voids

Workshop: Ultrasonic Imaging of Concrete Oakland, CA September 12, 2008




#### Typical Data Interpretation – Internal Cracks

Workshop: Ultrasonic Imaging of Concrete Oakland, CA September 12, 2008

#### 1<sup>st</sup> Case History – Determination of Internal Integrity of Concrete Transfer Wall

- Impact Echo (IE) tests were conducted using an Impact Echo Scanner (IES) system.
- Grid spacing of 18 inches between each scan line and approximately 1 inch spacing between tests along the scan
- Over 4,000 IE data points were obtained from the 50 x 12 ft test area in approximate 2 hours of field time

#### 1st Case History – Determination of Internal Integrity of Concrete Transfer Wall



Workshop: Ultrasonic Imaging of Concrete Oakland, CA September <u>12, 2008</u>

#### 2<sup>nd</sup> Case History - Void Detection in Post-tensioned Bridge Ducts




#### **Courtesy of Florida Department of Transportation**


Workshop: Ultrasonic Imaging of Concrete Oakland, CA September 12, 2008


{∭


- Fully Grouted Duct
  - Frequency peak = 6,445 Hz
  - Apparent Thickness = 11.17 inches (11% increase)
- Empty Duct
  - Frequency peak = 5,274 Hz
  - Apparent Thickness = 13.65 inches (36% increase)
- 20% increase in the thickness between the fully grouted and empty ducts


Note: Nominal thickness of the girder is 10 in with 4 in diameter duct











#### 0 0.8 Impact Echo Thick-1.6 ness Top Duct Second Duct from Top (inches Coly Map 14.0 2.4 Third Duct from Top 13.25 3.2 12.5 **Bottom Duct** 11.75 11.0 4 10.25 9.5 8.75 4.8 20 40 60 80 100 120 140 160 180 200 220 240 0 **East End** West End Length of Wall (inches)


Wall Height (ft)

#### 3<sup>rd</sup> Case History: Detection of Internal Voids between PT-Ducts on Concrete Box Girder

- Precast concrete box girder with four 3" diameter PT ducts in each web.
- PT ducts empty at the time of testing, concern is for voiding between ducts due to poor vibration during placement.
- Web wall 7.5" thick, approximately 6' tall.
- Scans performed vertically at 1 foot intervals.




- IES data from web wall.
- Vertical scan showing wall thickness and duct bank.
- Wall = 7.5" thick, the empty ducts show a substantial thickness increase.



# **Impact Echo Image Results**


- The 7.5" thick wall is shown in purple.
- The empty ducts are shown in Blue.
- Four distinct ducts are observed, therefore no voiding between the ducts at this location.
- Conclusion is that all voiding between the ducts was apparent from the surface.




#### 4<sup>th</sup> Case History: Detection of Internal Voids within PT-Ducts on Concrete Box Girder

- Precast concrete box girder with four 3" diameter PT ducts in each web.
- PT ducts grouted, concern is for voiding within the grouted ducts.
- Web wall 7.5" thick, approximately 6' tall.
- Scans performed vertically at 10 foot intervals, to spot check the grout condition.
- Significant voids discovered.


- IES data showing the typical wall thickness and four fully grouted ducts.
- The fully grouted ducts show a slight increase in thickness.
- Sound condition.



- IES data showing the typical wall thickness.
- The four ducts are near the bottom of the scan. The distance between ducts varies over the length of the girder.
- A confirmed voided duct is highlighted by the red cursor.
- Voided condition.




- IES data showing the typical wall thickness.
- The four ducts all display thin echoes, thought to be duct debonding or other defect condition.
- Questionable condition.



#### 5<sup>th</sup> Case History: Detection of Internal Cracks within Concrete Pavement Exposing to the ASR Problem

- ASR is a reaction between reactive <u>silica</u> (in the <u>concrete</u> aggregates) and an <u>alkali</u> (usually present in the <u>cement</u>), which results in the formation of a gel
- This gel increases in volume with water and exerts expansive pressure on the concrete, causing failure of the <u>concrete</u>
- Typical visual indicator of ASR includes a network of cracks on the concrete surface
- In many cases, ASR causes internal cracking damage prior to the development of surface cracks.
- Detection of the internal micro-cracking could lead to early detection of an ASR problem Early detection of the problem can, in turn, lead to an improved management and maintenance program for the structure

#### 5<sup>th</sup> Case History: Detection of Internal Cracks within Concrete Pavement Exposing to the ASR Problem




Results from the IES Tests


Visual Inspection of Surface Crack

#### 6<sup>th</sup> Case History: Detection of Internal Cracks and Backside Spalling on a Precast, Prestressed Concrete Beam

- The concrete beam rotated on its bearing support and applying torsional stresses within the
- A portion of the concrete was spalled.
- There was no access to the side of the concrete beam which underwent damage.
- Impact Echo testing from the opposite side of the beam was done to image the spall and any internal cracking.








#### Single Predominant Resonance

#### Multiple Predominant Resonances


# Impact Echo Image Results

- Plot of the most predominant resonant frequencies from the Impact Echo results.
- Sound concrete as well as likely spalled or severly cracked areas are aparent.



# **Impact Echo Image Results**

- Plot of the second most predominant resonant frequencies from the Impact Echo results. If no secondary peak occurred, than the primary resonance is plotted.
- Sound concrete as well as likely spalled or severly cracked areas are aparent.







# Questions???